

POMS & RAPID Integration

© 2016 Rolls-Royce plc

The information in this document is the property of Rolls-Royce plc and may not be copied or communicated to a third party, or used for any purpose other than that for which it is supplied without the express written consent of Rolls-Royce plc.

This information is given in good faith based upon the latest information available to Rolls-Royce plc, no warranty or representation is given concerning such information, which must not be taken as establishing any contractual or other commitment binding upon Rolls-Royce plc or any of its subsidiary or associated companies.

POMS & RAPID Interface

- If you are member of both POMS & RAPID, you can seamlessly view the following information from either:
 - POMS Obsolescence information is sent to OIRD
 - POMS Obsolescence Solution information is sent to OIRD
 - CMIS Lite Solutions are sent to OIRD
 - OIRD Obsolescence information is sent to POMS
- You can also log in to one system, and automatically transfer to the other without re-logging in



How Much Information is This?

- POMS sends RAPID 133,087 obsolete items
- POMS sends RAPID 43,243 items with solutions
- RAPID sends POMS 17,307 obsolete items
- RAPID sends POMS 13,442 obsolete solutions
- CMIS sends RAPID 1,040 equivalency evaluations in 2015



Picture of search results with OIRD obsolete

POMS		Logged in as:	& <u>Chan</u>	<u>qe Info</u> 📕	Log Out 🧍 Live Chat
Proactive Obsolescence Management	System 🥭 Search	All	Sites	✓ 🗾	Search Advanced
👫 Home 📄 Reports 🛛 🔎 Se	arch 🔲 🖬 Results 🛛 🛱 C	Obsolescence Manager 🔻	∠ Tools -	? Help	📝 Feedback
Home Search Results					
POMS Search Criteria	Search Term:"1151"		Go	To Page	Submit
Sort Criteria 276-300 of 6223	Export To Excel W1151VB by INTERNATION				
$ \stackrel{\text{(143)}}{\pm} \underbrace{\text{Maintenance Plan (12)}}{\text{(143)}} \\ \stackrel{\text{(143)}}{\pm} \underbrace{\text{Action Plans (0)}}{\text{(143)}} \\ \stackrel{\text{(143)}}{\pm} \underbrace{\text{Site (521)}}{\text{(143)}} $		poration			Model
	Show More				
	X1151VB by INTERNATION CONDENSATE STORAGE TANK		ROOM INDICATION	EDGEWISE INC	DICATOR-MAIN
	POMS OBSOLETE Colla	boration			Model
	Show More				_




 Picture of OIRD pop-up over POMS search results when you click OIRD obsolete

me 📄	Reports 🥠	Search 📔 🖬	tesults 🛛 🗐 Obs	olescence Manager -	^ん Tools • 📔 🕄 Help	📝 Feedback	
Search Resu	ults)	
MS Search (Criteria	Search Term	:"1151"		Go To Page [Submit	
t Criteria 2	276-300 of 6223	Export To	Excel			4 12 of 249 🕨	
Component	<u>it (364)</u> rer / Model (570)			INCTRUMENTS			
Stock (145)	1		Y INTERNATIONAL				
Maintenand Action Plan	<u>ce Plan (12)</u> os (0)	POMS OBSOLETE		tion		odel	
Site (521)	10 107					S	
		E Show More					
		-	And in case of the local division of	NAME AND ADDRESS OF TAXABLE PARTY.			
		Construction of the	strong tame and	a manufacture and	No. of Contractor	MELLING MARK	
	66 62 63	Property	Complete State	her.			
	1 Pm	Toll.	-			Welcome:	
				and the			Your Account Sign out
	211	12/1	and the second se				How can we help?
	Parts	Contrast of	A CON		P 2	dvanced	non cur no nupr
	and the second second second second				P	dvanced	
	and the second second second second	Ob	solescence Search Re		٩		evious Next > [+]
	Parts Filters Safety Related	ов 	solescence Search Res - With Solutions 0	- Without Solutions		Page 1 of 1 < Ph	evious Next> [+]
	Parts Filters Safety Related Part Number.	L	solescence Search Re		Owner South Carolina Electric	Page 1 of 1 < Pro Offer	evious Next > [+] Solution
	Parts Filters Safety Related Part Number Manufacturer.	0b 1	solescence Search Rei - With Solutions 0 Part #/Mfr	- Without Solutions Description INDICATOR, VERTICAL; 4-20MADC, BLK SC, 1151VB, S	Owner South Carolina Electric	Page 1 of 1 < Pro Offer	evious Next> [+]
	Parts Filters Safety Related Part Number.	0b 1	solescence Search Re: - With Solutions 0 Part #/Mfr L1151VB	- Without Solutions Description INDICATOR, VERTICAL;	Owner South Carolina Electric	Page 1 of 1 < Pro Offer	evious Next > [+] Solution
	Parts Filters Safety Related Part Number Manufacturer. Part Name		solescence Search Re: - With Solutions 0 Part #/Mfr L1151VB	- Without Solutions Description INDICATOR, VERTICAL; 4-20MADC, BLK SC, 1151VB, S	Owner South Carolina Electric	Page 1 of 1 < Pro Offer	evious Next > [+] Solution



 Picture of manufacture model page with multiple solutions and some of them OIRD

PON	IS			Logge	d in as:	& <u>Chan</u>	ige Info 🛛 📕 L	og Out 🏄 Live C
Proactive Ob	osolescence Man	nagement System	₽ Searc	:h	AI	l Sites	✓ 2:	Search 2 Advanc
Home	Reports	● Search	Results	🗐 Obsolesco	ence Manager 🔻	∠ ^c Tools ▼	? Help	📝 Feedback
$_{ m ne}$ $ angle$ Search Re	sults > Manufac	cturer / Model						
Information						💄 Potentia	I Solutions	
	Contact Info	Vendor Questions	Vendor Notes	Feedback			Returned: 8	
						🖣 1 of 1	Jump	p To: 📃 🌩
						Solution	Source	View
Model Informa Manufacturer:	GENERAL ELE	CTRIC				GENERAL	12IACOIRD	View entry
Model:	12IAC66K8A							in OIRD View entry
Description:	SULLAIR COM	PRESSOR OVERCU	JRRENT RELAY 51				12IACOIRD	in OIRD
Model Details							ELECT POMS	
Serial Number	Part Size	Material	Catalog ID	Other	Obsolete		ActioAction Pla	an <u>View Action</u>
N/A			_		9	Automatic	ActioAction Pla	
					9			
					0			
Inductor BOM								





• Picture of man model page with OIRD pop-up on top

A X A	Obsolescence Search	Results		Advance	The second secon	1-81.8-	we help?	er/Mod × Change Info 🔎 Log Out 🧍 Live Cha V 💭 Search 💭 Advanced T Help 🎲 Feedback
Safety Related	1 - With Solutions	0 - Without Solutions						
Part Number	Part #/Mfr	Description		Owner	(Offer Solution		
Manufacturer Part Name P. All - 1 Relay 1	12IAC66K8A General Electric	RELAY, OVERCURRENT; S PHASE, 60 HZ, LONG TIME 2.5-5 AMPS RELAY SETTIN AMPS INSTANTANEOUS, 4 AMPS HIGH	DELAY, Cooper Npp G, 20-80	blic Power District		♀ Solutions		Intial Solutions ions Returned: 8 of 1 Jump To:
Industry Type							~	RAL 12IACOIRD
						6	100% ▼	RAL 12IACOIRD <u>View entry</u> in OIRD RAL ELECT POMS
		Model Details			_	_	GEN	IERAL ELECT POMS
		Serial Number Part Size	Material	Catalog ID	Other	Obsolete	Aut	comatic ActioAction Plan View Action
		N/A				4		
						9		
	11.	Industry BOM Information Industry BOM Information	Associated Stock	Codes Installe	d Locations			1
		Stock From BOM:	8 Stock Fro	om Work Orders:	61	Stock From	Both: 🗌 6	Total Stock Returned: 75



• Picture of RAPID search result with POMS data



Filters		Obsolescence Search Re	sults		Page 1 of 7 < Previous Next > [+]
Safety Related		70 - With Solutions	44 - Without Solutions		
Part Number		Part #/Mfr	Description	Owner	Offer Solution
Manufacturer		C09997-0001	GAUGE, PRESSURE; 0-600 PSI LINEAR SCALE, 4-20 MADC INPUT,	Arizona Public Service	Solutions
Part Name ✓ - All -	114	Rosemount	METAL HOUSING, FOR ROSEMOUNT MODEL 1151 TRANSMITTERS	Palo verde Ngs	
Differential	24 9	50-555-111BDAA4AAA Gemac	DIFFERENTIAL PRESSURE TRANSMITTER	Detroit Edison Fermi 2 Npp	♀ Solutions
Pressure Pressure		01151-0137-0001 Rosemount Analytic	BOARD, PRINTED CIRCUIT, AMPLIFIER, 26871060	PKMJ Technical Services, Inc. Corporate	♀ Solutions
Gauge Level Tranmitter	1 1 1	1151GP7 Rosemount Analytic	NMP-INSTRU-IXMITR, CAPACITANCE PRESSURE TRANSMITTER GE DESIGNATOR C12-N054A	PKMJ Technical Services, Inc. Corporate	♀ Solutions
Industry Type		01151-0112-0192 Rosemount Analytic	MODULE, SENSOR, 26871585	PKMJ Technical Services, Inc. Corporate	♀ Solutions



 Picture of POMS pop up with obsolescence data with RAPID in the background

Obsolescence Advanced How can we help? Solution Maintenance Image: Comparison of the second of the
Obsolete Item Information Return To Your Search Results Description Owner 1151 GP6 TRANSMITTER, FNPIMS TPNS / EQ PKMJ Technical Services, Inc. Solution Details NAME: SGFP "A" BEARING OIL PRESSURE TRANSMITTER FNPIMS TPNS / EQ DESC: Corporate Solution Id: 58854 Date Entered: 1/13/2013 Solution: Equivalent Replacement Last Updated: 3/20/2013 Part #: 3051S OR 1152 SERIES Stock #:
Obsolete Item Information Part #/Mfr Description Owner 1151 GP6 TRANSMITTER, FNPIMS TPNS / EQ PKMJ Technical Services, Inc. Solution Details NAME: SGFP "A" BEARING OIL PRESSURE TRANSMITTER, FNPIMS TPNS / EQ DESC: Corporate Solution Id: 58854 Date Entered: 1/13/2013 Solution: Equivalent Replacement Last Updated: 3/20/2013 Part #: 3051S OR 1152 SERIES Stock #:
Part #/Mfr Description Owner Return To Your Search Results 1151 GP6 TRANSMITTER, FNPIMS TPNS / EQ PKMJ Technical Services, Inc. Solution Details NAME: SGFP "A" BEARING OIL PRESSURE TRANSMITTER FNPIMS TPNS / EQ DESC: Corporate Solution Id: 58854 Date Entered: 1/13/2013 Solution: Equivalent Replacement Last Updated: 3/20/2013 Part #: 3051S OR 1152 SERIES Stock #:
Part #/Mfr Description Owner 1151 GP6 TRANSMITTER, FNPIMS TPNS / EQ PKMJ Technical Services, Inc. NAME: SGFP "A" BEARING OIL PRESSURE TRANSMITTER FNPIMS TPNS / EQ DESC: Solution Details Search Supplier Catalog Solution Id: 58854 Date Entered: 1/13/2013 Search Supplier Catalog Solution Id: 58854 Date Entered: 3/20/2013
Rosemount Nuclear NAME: SGFP "A" BEARING OIL PRESSURE TRANSMITTER FNPIMS TPNS / EQ DESC: Corporate Solution Details Solution Id: 58854 Date Entered: 1/13/2013 Solution: Equivalent Replacement Last Updated: 3/20/2013 Part #: 3051S OR 1152 SERIES Stock #:
FNPIMS TPNS / EQ DESC: Solution Id: 58854 Date Entered: 1/13/2013 Search Supplier Catalog Part #: 3051S OR 1152 SERIES Stock #:
Search Supplier Catalon
Part Name: Mfr: ROSEMOUNT NUCLEAR
Search Search Cancel Type/Size: Addl Doc#:
Catalog Search Results Page 1 of 1 < Previous Next
Comments: ROSEMOUNT RECOMMENDS EITHER THE 1152 OR 3051S SERIES AS
Available Solutions REPLACEMENT OPTIONS. THE 3051S IS NOT SUITABLE FOR LOW RADIATION
Available solutions ENVIRONMENTS, IN LOW RADIATION ENVIRONMENTS THE 1152 SERIES WOULL Owner Solution Status Date BE THE RECOMMENDED REPLACEMENT. THERE IS NO DIRECT REPLACEMENT
PKMJ Technical Services, Inc. Design Pkg Prepared/EE 1/13/2013 For THIS MODEL AND EXACT REPLACEMENT MODEL NUMBER WOULD BE BASED ON APPLICATION AND CONFIGURATION OF THE EXISTING UNIT.
Attachments:
Contact Information
Name: Rob Santoro Company: PKMJ Technical Services, Inc.
Job Title: Sr Manager Plant: Corporate
Email: santoror@pkmj.com Phone #: 412.865.3040
■ View Additional Contact Information
Close



Picture of a CMIS item in OIRD

arts Obsolescence	2	8211B54MO		Advanced		unt Sign out v can we help?	
	Obsolescence Searce 1 - With Solutions	ch Results 0 - Without Solutions		Pa	age 1 of 1 < Previous N	lext > [+]	
rt Number nufacturer	Part #/Mfr 8211B54MO Asco	Description Not Available		Owner Fechnical Services, Inc.	Offer Solution		
Obsolete Details							
Obsolete Id: 167463 Obs Because: Part #: 8211B54M Part Name: Type/Size: Description: Comments:	o	Date Entered: 10/30/201 Last Updated: 1/23/2016 Owner Type: Nuclear Pl Stock #: Mfr: ASCO Sfty Related: N	5	Solution Details Solution Id: 36860 Solution: Equivaler Part #: EF8210B Part Name: Type/Size: Eval #:		Date Entered: 1/1 Last Updated: 1/2 Stock #: Mfr: ASC Addl Doc#:	3/2016
Contact Information Name: Rob Santoro Job Title: Sr Manager Email: santoror@pkmj I View Additional Contact I		<i>Company:</i> PKMJ Techni <i>Plant:</i> Corporate <i>Phone #:</i> 412.865.304		Description: Comments: Attachments: 1. PKMJT Contact Information			
Available Solutions				Name: Rob Santoro Job Title: Sr Manager Email: santoror@pl		Company: PKMJ T Plant: Corpor Phone #: 412.86	
Owner PKMJ Technical Se Corporate		Solution Status Design Pkg Prepared/EE	Date 1/13/2013	View Additional Conta	act Information	Close	
	🔗 Watch List 🧉	Vedit Close					



How else do we work together?


Picture to log in to RAPID from POMS (under the tools menu)

& POMS	Logged in	1 as: 🦼	Change Info	Log Out 🥵 Live Chat
Proactive Obsolescence Management System	" ●Search	All Sites	~	Search Advanced
👔 Home 📄 Reports 📃 🔎 Search	🖬 Results 🛛 📮 Obsolescenc	e Manager 🗸 🛛 🥕 Tool	- 🕐 Help	📝 Feedback
		Catalog H	ealth	
Home		CMIS Lite	l.	
A My Obsolescence		Critical S	pares	hes
	l in on 5/13/2016 1:11:56 PM	Industry	Obsolescence Inde	
Welcome you last logged	11 01 3/13/2010 1.11.30 PM	PM Dema	nd	NTATION 34P34
PM Forecasting		PM Preve	ntive Maintenance	ation 34p344
2		Work Pla	nning Optimization	es
Near-Term PM Impacts By Site:		rapidpar any part, a	tsmart.com any where.any time.	A



How else do we work together?

Picture of RAPID with the POMS link to get in to POMS



Fleet Level Reports

Industry Level Reports

What's New In Obsoleso	ence					Upcoming Events
0 - On My Watch List	0 - Impacting My Company	47 - Al	1			
Part #/Mfr	Description		Owner			Silver Anniversary-25th A
5K215DP5709 Ge Energy Services	MOTOR, 15HP, FRAME 215 PHASE, 460VAC, 18.2 FL	LP, 3	AmerenUE Callaway Npp	Solutions	^	Technical Exhibit May 15 - 18, 2016 Sheraton Sand Key Resort
9534232039 Robert Bosch	BLADDER, FOR ROBERT B GALLON BLADDER STYLE		AmerenUE Callaway Npp	V Solutions		Clearwater Beach, FL Download Event to Outlo
MX001719 Hy-Security	CHARGER,BATTERY,24VD 115V 60HZ INPUT	C,25 AMP,	AmerenUE Callaway Npp	♀ Solutions		62nd FOMIS Conference June 13 - 16, 2016
4356006-150-567 Masoneilan	BUSHING, VALVE, TYPE: U GUIDE, VALVE	PPER	AmerenUE Callaway Npp	V Solutions		Sheraton Sand Key Resort Clearwater Beach, FL Download Event to Outlo
F S98H-142 Fisher	VALVE, RELIEF, SAFETY, ½ TO 75 PIS ADJUST	4-INCH, 25	American Electric Power D. C. Cook Npp	V Solutions		Nuclear Utility Procureme July 11 - 13, 2016 EPRIS Charlotte Office - B
60-3404-033 Isco Inc.	SENSOR, LEVEL		Duke Energy Mcguire Npp	♀ Solutions	\sim	Charlotte, NC Download Event to Outlo
DWC 26660 FAA			Duke Eperati			Procurement of Reactor (Replacement Items Train
My Watchlist		Obsole	scence Toolkit			July 14 - 15, 2016
Part #	Mfr	Links	Reports POMS]	~	EPRI Charlotte Office - Bldg Charlotte, NC
	list is empty.		Launc	h POMS		Download Event to Outlo 2016 NUOG Annual Meet July 18 - 20, 2016
6 Watch List button.	-		V Impac	t Report		Crystal Gateway Marriott Washington, D.C. Download Event to Outlo
						Dominour Literit to Outlo

**

Member Contact Information

Recent Searches

rwater Beach, FL nload Event to Outlook FOMIS Conference 13 - 16, 2016 aton Sand Key Resort rwater Beach, FL nload Event to Outlook ear Utility Procurement Training Course 11 - 13, 2016 IS Charlotte Office - Building 3 lotte, NC nload Event to Outlook urement of Reactor Coolant Pressure Boundary acement Items Training 14 - 15, 2016

er Anniversary-25th Annual RAPID Conference &

Charlotte Office - Bldg. 3 lotte, NC nload Event to Outlook NUOG Annual Meeting

Nuclear Utility Procurement Training Course December 06 - 08, 2016 EPRI Charlotte Office - Bldg 3 Charlotte, NC Download Event to Outlook

Supplier Spotlight



Pooling and SEER Integration?

Inventory Pooling is a managed service by Rolls-Royce to optimize and share inventory across utilities with the ultimate goal of utilizing and reducing inventory across the industry.

Seer provides visibility from within a utility's ERP system to potentially duplicated stock codes and as well as to alternative sourcing options from industry inventory.

Contingency Parts Manager facilitates the reservation of inventory between utilities to mitigate inventory growth from contingent purchases.

MRP Cont.	MRP controller name						
D99	DB Pooling						
D99	DB Pooling						
D99	DB Pooling						
P99	Perry Pooling						
P99	Perry Pooling						
P99	Perry Pooling						
899	BV Pooling						
899	BV Pooling						
899	BV Pooling						

-		-	and annothing the second		the state of the s	and the second second	_
	Maintain	M	aterial	Requirements	Planning	Data	

« / A 7 H & 70 Z0 % 0 A 0 40 H H

Available on SEER

💥 Exit

3	Light	SEER	Material	Material Description	Plant	MRP Cont.	MRP controller name	Qual Ind	SPT	Unrestr.	Reorder	Maximum stock level	PDT	Avg PO LT
	00	1	90389101	CONNECTOR:PLUG-IN,9-PI	G201	D99	DB Pooling	Q	AA	4.000	1	2	35	17 (2 POs)
1	00	1	32054806	O-RING: SPECIAL PURPOS	G201	D99	DB Pooling	N	AA	5.000	2	4	18	(0 POs)
3	00	1	32031301	VALVE-GATE: 1 IN, BOLTE	G201	D99	DB Pooling	N	NC	3.000			30	(0 POs)
3	000	1	100072924	RELAY, 125VDC, ON-DELAY	G202	P99	Perry Pooling	Q	BB	1.000			45	(0 POs)
1	000	1	97162345	PACKING	G202	P99	Perry Pooling	N	NC	1.000			7	(0 POs)
3	000	1	8502027	VALVE, GATE, 1/2 IN, AS	G203	B99	BV Pooling	N	BA	11.000	2	7	40	14 (1 POs
3	000	1	8310067	BOARD, PRINTED CIRCUIT,	G203	B99	BV Pooling	N	AA	3.000	1	1	393	(0 POs)
1	000	1	8310017	BOARD, PRINTED CIRCUIT,	G203	B99	BV Pooling	N	AC	1.000			419	(0 POs)



Pooling and SEER Integration?

Change MRP Se	ttinas				RP Co					P	aseros.	0.305.05
Go Back Save & I		MD04	MD05 ME54N	ZM131	MMBE	BFO	ZM48	StkPin	MM02	Product	ZM164	SEER
OU DACK I DI Save & I		MDOT	MD05 MESH	20151		bro	20140	JUSCKFIII	141402	Floduce	20104	JEEK
Reference MRP Informat	ion											
Material 84463906	BEARIN	G-JOURA	AL:AUXILIARY GEAR	R	UOM	EA E	ach [Function	Location	Info		
Plant G202 Perry Nyclear			Pwr Plt Qual Indicator N					Num Fun Loc 1			Critical	SPV
MAP \$ 3,606.79				Critic	al Part			Criti	cal	1		
MRP Controller P99	P Parry Poo	ling	Last MRP Update					Non-Critic	al	0 Nor	Impact	0
Shelf Life 0	Days		Last Update User						1012 00100			
								MRP Stati	stics			
X Plant Mat Status			Repairable Indicator					Unrest Use Stock				1.000
Plant Spec Mat Status			Maint Philosophy					Main Unrest Use				1.000
Revised Status			Maintenance Rule No					Total Resv Qty			0.000	
Actual 12 Months Usage 0.0			Total Cont Parts 0.000					QM Stock			0.000	
								Blocked Stock			0.000	
Review Consumption	tion History							Stock in				0.000
								Open Re				0.000
Return Ratio (4 yr) Issues Are Zero			Outline Agreement					Open PO Qty			0.000	
Excess Qty / Value No Excess / 0.00			OA Lead Time 0					Resv (Mvmt Allow))	0.000	
Issued / WO	0/0					-		GDC QTY	0			0.000
PIPE				PO Lines - 4 Years 0				2.2				
Open PEF(s)	0						Y	Follow-Up	Material			
MRP Parameter Adjustm	ents				Stocking (Criticality	y Adjust	ments				
Current			Revised					C	Current	Revised	đ	
MRP Type	VB		ABC Indicator					А	U.			
Reorder Point	1		MR		MRP Gro	RP Group						
Calculated EOQ	lculated EOQ 0		SPT Code					A	A			
Lot Size HB		SPT Reviewed							02/12/	2015		
Minimum Lot Size 0.000			Planned Delivery Time			y Time		9	0			
Maximum Stock Level 1				Last Update Date						08/18/	2011	
Rounding Value 0				Avg Lead Time (# POs)				1	(0 POs)			



Questions



